



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

August 12, 2021

Mr. Cory Hoffman
General Manager
Toyota Motor Engineering & Manufacturing
19001 South Western Ave
Torrance, CA 90501

NEF-107SS
21V-617

Subject: Fuel Pump May Fail and Cause Engine Stall

Dear Mr. Hoffman:

This letter serves to acknowledge Toyota Motor Engineering & Manufacturing's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

TOYOTA/YARIS/2019-2020

Mfr's Report Date: August 6, 2021

NHTSA Campaign Number: 21V-617

Components:

FUEL SYSTEM, GASOLINE:DELIVERY:FUEL PUMP

Potential Number of Units Affected: 31,307

Problem Description:

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2019-2020 Yaris, Yaris Hatchback, and Yaris Sedan vehicles. An impeller within the low-pressure fuel pump may crack and deform, potentially causing the fuel pump to fail.

Consequence:

A fuel pump failure may cause an engine stall, increasing the risk of a crash.

Remedy:

Dealers will replace the low-pressure fuel pump assembly, free of charge. Owner notification letters are expected to be mailed September 30, 2021. Owners may contact Toyota customer service at 1-800-331-4331. Toyota's numbers for this recall are 21TB05 and 21TA05.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



Please ensure the following requirements are met:

The percentage of products estimated to contain the defect or noncompliance (49 CFR 573.6 (c)(4)). If less than 1%, amend your filing to state 1% and provide the actual calculated amount in the first product text box.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Toyota Motor Engineering & Manufacturing's contact for this recall will be Sarah Shiver who may be reached by email at sarah.shiver@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement